





# Before Fix:



# Before Fix:



After resistors swapped & TLP291 added but before black wire moved from GND to IN+:



PIN 1 OF TLP291

# After All Fix:

