





Jumper a saldare GND to DISSIPATORE




Termoresistenza PT 1000 - FEB J1/J4



Jumper a saldare GND to DISSIPATORE



PMT_A
PMT_R11265_CUT



PMT_B
PMT_R11265_CUT

