



- Xtra1 Enclosure
- Xtra2 Display
- Xtra3 Display DIP16
- Xtra4 IEC Inlet
- Xtra5 Fuseholder
- Xtra6 Fuse
- Xtra7 Knob for VR4
- Xtra8 Cap for Xtra7
- Xtra9 (SSR)
- Xtra10 Cap for SW2
- Xtra11 IDC socket16
- Xtra12 Lemo Sleeve
- Xtra13 Arduino Pins
- Xtra14 Heat Sink